

NATURAL CANDLE COLLECTION

To prevent tunneling, allow time for wax to melt completely as it forms a pool to the edge of the vessel.

Burn your candle for at least two hours on the first use.

Trim the wick by 1/4 inch before each burn.

Burn only on heat resistant surfaces.

WWW.LUXEBUTTA.COM

